

Safety Recall Quarterly Report Information

Report Date: July 14, 1999

Calendar Quarter: 1

Safety Recall Quarterly Report from April 1999 through June 1999

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: SKF Hubs/Meritor Axles

1. NHTSA Safety Recall Campaign No.

99V-128,002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 99KW2

2. (a) The date notification to purchasers began:

6/17/99

(b) The date notification to purchasers was completed:

6/25/99

3. The total number of items¹ involved:

10

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale:

0

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied:

0

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY:

0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable:

0

Total number exported:

0

Total number stolen:

0

Total number scrapped:

0

Total number unable to notify:

0

Total number otherwise unreachable:

0

Describe other:

¹ (Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.)

Safety Recall Quarterly Report Information

Report Date: October 15, 1999

Calendar Quarter: 2

Safety Recall Quarterly Report from July 1999 through September 1999

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: SKF Hubs/Meritor Axles

1. NHTSA Safety Recall Campaign No.

99V-128.002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 99KW2

2. (a) The date notification to purchasers began:

6/17/99

(b) The date notification to purchasers was completed:

6/25/99

3. The total number of items¹ involved:

13

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale:

9

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied:

1

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY:

0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable:

0

Total number exported:

0

Total number stolen:

0

Total number scrapped:

0

Total number unable to notify:

0

Total number otherwise unreachable:

0

Describe other:

¹ Items shall refer to the vehicles, buses or equipment or tires involved in the safety recall on which you are reporting.
SKF hubs-meritor axles-400

Safety Recall Quarterly Report Information

Report Date: January 24, 2000Calendar Quarter: 3Safety Recall Quarterly Report from October 1999 through December 1999Manufacturer: PACCAR Inc (Kenworth)Report Author: Kenneth R. Brownstein Phone (425) 468-7356Recall Subject: SKF Hubs/Meritor Axles

1. NHTSA Safety Recall Campaign No.

98V-128002Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 99KW22. (a) The date notification to purchasers began: 6/17/99(b) The date notification to purchasers was completed: 6/25/993. The total number of items¹ involved: 13

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 0

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 6

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable: 0Total number exported: 0Total number stolen: 0Total number scrapped: 0Total number unable to notify: 0Total number otherwise unreachable: 0

Describe other: _____

¹ Items shall refer to the vehicles, parts or equipment or tires involved in the safety recall on which you are reporting.
NHTSA: 425-468-7356, 425-468-7357

Safety Recall Quarterly Report Information

Report Date: April 18, 2000

Calendar Quarter: 4

Safety Recall Quarterly Report from January 2000 through March 2000

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: SKF Hubs/Meritor Axles

1. NHTSA Safety Recall Campaign No.

99K121.002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 99KW2

2. (a) The date notification to purchasers began:

6/17/99

(b) The date notification to purchasers was completed:

6/25/99

3. The total number of items¹ involved:

13

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale:

0

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied:

8

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY:

0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable:

0

Total number exported:

0

Total number stolen:

0

Total number scrapped:

0

Total number unable to notify:

0

Total number otherwise unreachable:

0

Describe other:

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: July 17, 2000

Calendar Quarter: 5

Safety Recall Quarterly Report from April 2000 through June 2000

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: SKE Hubs/Meritor Axles

1. NHTSA Safety Recall Campaign No.

99V-128.002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 99KW2

2. (a) The date notification to purchasers began: 6/17/99

(b) The date notification to purchasers was completed: 6/25/99

3. The total number of items¹ involved: 13

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 0

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 8
Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 0
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable: 0

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify: 0

Total number otherwise unreachable: 0

Describe other: _____

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: October 13, 2000

Calendar Quarter: 6

Safety Recall Quarterly Report from July 2000 through September 2000

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: SKF Hubs/Meritor Axles

1. NHTSA Safety Recall Campaign No. 99V-128.002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 99KW2

2. (a) The date notification to purchasers began: 6/18/99

(b) The date notification to purchasers was completed: 6/25/99

3. The total number of items¹ involved: 13

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 0

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 8

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable: 0

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify: 0

Total number otherwise unreachable: 0

Describe other: _____

¹ Items shall refer to the vehicles, items or equipment or lines involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information.

Report Date: April 20, 2001

Calendar Quarter: 8

Safety Recall Quarterly Report from January 2001 through March 2001

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: SKF Hubs/Meritor Axles

1. NHTSA Safety Recall Campaign No. 99V-128.002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code:

99KW2

2. (a) The date notification to purchasers began: 6/18/99

(b) The date notification to purchasers was completed: 6/25/99

3. The total number of items¹ involved: 13

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 0

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 7

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable:

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify: 0

Total number otherwise unreachable: 0

Describe other: _____

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: July 17, 2001

Calendar Quarter: 9

Safety Recall Quarterly Report from April 2001 through June 2001

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: SKF Hubs/Meritor Axles

1. NHTSA Safety Recall Campaign No. 99V-128.002
 Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 99KW2
2. (a) The date notification to purchasers began: 6/18/99
 (b) The date notification to purchasers was completed: 6/25/99
3. The total number of items¹ involved: 13
 The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).
 Number of Items Returned from Inventory or Remedied Prior to Sale: 0
 Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.
 Do not include this number in 4(a) or 4(b).
4. (a) Total number inspected & remedied: 7
 Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).
 (b) Total number inspected & NOT REQUIRING REMEDY: 0
 Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
5. Items Determined to be Unreachable:
 Total number exported: 0
 Total number stolen: 0
 Total number scrapped: 0
 Total number unable to notify: 0
 Total number otherwise unreachable: 0
 Describe other: _____

¹ Items shall refer to the vehicles, items or equipment or items involved in the safety recall on which you are reporting.